

## Transformer Remedial Works Report

1BFT10GT001 / 19 Aug 2024 /  
Michael Straw

Complete

<b>Flagged items</b>	0	<b>Actions</b>	0
----------------------	---	----------------	---

**Client Name**

---

**Date of Visit**

---

**Prepared by**

Michael Straw

---

**Location**

---

## Questions

Substation: Unit

**Make**

GBE



Photo 1



Photo 2

**Serial Number**

12333. 1/1

**Size (KVA)**

2500

**Voltage Ratio (Primary / Secondary)**

11000/690

**Vector Group**

Dyn11

**Year of Manufacture**

2018

**Total Mass**

5890kg

**Cooling Medium**

A.N

**Cooling Method**

Air

**Quantity of Cooling Fluid**

-

**Tap Change Setting**

-

**Tap Change Mechanism**

-

Remedial Works

### Provide details of remedial work completed on this visit

Transformer IR, Ductor, Ratio and Tan-Delta tested ( Images Below). Clean Down and removal of any dust from inside and out of transformer enclosure.



Photo 3



Photo 4



Photo 5




Photo 6




Photo 7




Photo 8




Photo 9



Photo 10



Photo 11



Photo 12



Photo 13




Photo 14



Photo 15



Photo 16



Photo 17




Photo 18




Photo 19



Photo 20



Photo 21




Photo 22



Photo 23




Photo 24



Photo 25




Photo 26



Photo 27



Photo 28



Photo 29




Photo 30



Photo 31




Photo 32



Photo 33




Photo 34



Photo 35



Photo 36



Photo 37




Photo 38

**Any other comments**

N/A

**Report completed by**

19.08.2024 14:38 BST

**Customer Signature**

19.08.2024 14:38 BST

## Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5




Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17




Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29



Photo 30



Photo 31



Photo 32




Photo 33




Photo 34



Photo 35



Photo 36



Photo 37



Photo 38